



# CB1950B SPARE PARTS-BODY

Page 1 of 2

Ref.	Code	Description	Specification	Q'ty	Note
101	CB950. 01. 00	Body		1	
102		Motor		1	
103		Disk key	C5X5X20	1	
104		Pulley		1	
105		Strap		1	
106		Washer	10	4	
107		Elastic washer	10	10	
108		Screw	M10X25	4	
109		Side panel		1	
110		Plank		1	
111		Screw	M5.5X19	2	
112	B-F. 01. 06	Spring		1	
113	B-F. 01. 05. 00	Support hose		1	
114	B-F. 01. 11	Fixing spacer		1	
115		Screw	M6X20	1	
116		Nut	M6	9	
117		Screw	M6X16	2	
118					
119		Screw	M10X50	2	
120	B-F. 01. 02	Hose		1	
121	B-F. 01. 01	Protection cover		1	
122		Screw	M5.5X19	6	
123		Nut	M4	2	
124		Elastic washer	4	4	
125		Flat washer	4	4	
126		Stroke switch		1	
127		Screw	M4X30	2	
128		Screw	M8X50	1	
129		Nut	M8	1	
130		Screw	M6X20	1	
131		Resistance clip		1	
132		Insulation paper		1	
133		Resistance		1	
134		Plug		4	
135		Power board		1	
136		Screw	M4X10	3	
137		Power cable		1	
138		Voltage transfer		1	
139		Flat washer	6	4	
140		U-shape plug		2	
141		Bracket		1	
142		Screw		2	
143		Screw		2	
144		Pressing plate		1	
145		Pressing plate		1	
146		Elastic washer	6	1	
147		Nut	M10	2	
148		Cover		1	
149		Computer board		1	
150		Screw	M3X35	4	
151		Panel		1	
152		Weights tray		1	
153		Screw	M5.5X25	4	
154		Balancing hammer		1	
155	B-P. 01. 03A	Small cone		1	
156	B-P. 01. 04A	Medium cone		1	
157	B-P. 01. 05A	Large cone		1	
158		Handle		2	
159		Switch		1	
160		Caliper		1	
161		Screw	M6X16	1	
162		Scale handle		1	
163	B-L. 01. 02	Scale		1	
164	B-L. 01. 05	Front spacer of scale		1	



# CB1950B SPARE PARTS-SHAFT



